

US EPA ARCHIVE DOCUMENT

UNIT LOG		1. Incident Name Kalamazoo River/Enbridge Oil Spill	2. Date Prepared 03/08/2012	3. Time Prepared 1730
4. Unit Name/Designators Situation Unit		5. Unit Leader (Name and Position) Melinda Leutke, Planning Section Chief		6. Operational Period 0700, 03/08/2012 – 0700, 03/15/2012
7. Personnel Roster Assigned				
Name		ICS Position		Contact Phone
Matthew Haak		Situation Unit		[REDACTED]
8. Activity Log				
Time	Major Events			
0900	<p>Observations:</p> <ul style="list-style-type: none"> Observed Turbidity Control Structure being demobilized. Turbidity Control Structure: observed floc-box being demobilized. Talmadge Creek: observed demobilizing of bypass discharge near MP1.6. Talmadge Creek: Observed that the weir structure near MP1.6 has been removed. Talmadge Creek: Observed timber mat removal and restoration near MP1.8. Confluence: observed the removal of the second diversion box. Confluence: observed sheet piling remaining. Confluence: observed excavation around the location of the second diversion box. Confluence: observed vacuum truck dewatering excavation area. Confluence: observed vacuum truck off loading into frac-tanks. Confluence: observed restoration of the scrape area near the red barn. Confluence: observed water quality monitoring. OB9.10 LDB: observed scraping operation. OB9.10 LDB: observed back filling of scraped area. OB9.10 LDB: observed sheen outside of delineated scrape area. OB8.97 I: observed standing water. 			
1500	Return to ICP.			
9. Prepared by (Name and Position) Matthew Haak, Situation Unit Leader, USEPA-START				